



scopito

THE FUTURE OF VISUAL INSPECTIONS



scopito

THE FUTURE OF VISUAL INSPECTIONS



Report date:
Mar 16, 2020

20

Number of
annotations



Status:
Published



Type:
Power Line



Company:
Scopito Demo 1




Inspection created:
Oct 9, 2019



Report Images:
5



Report created by:
Ditte Rabæk
drl@scopito.com



Severity overview

Severity 1

7

Severity 2

9

Severity 3

0

Severity 4

1

Severity 5

0

POI (?)

3

💡 Inspection summary

This is a demo point inspection on various elements within the power grid.
This is where Summary can be added and edited.

For further information please contact info@scopito.com

Annotation overview


Id	Severity	Issues	Comments	Page
882878	?	POI	Wear from vibration damper clamps	4
882879	?	POI	AGS Clamp	5
882887	2	rust on bolt		6
882888	2	rust on bolt		6
882889	2	rust on bolt		7
882890	2	rust on bolt		7
882891	2	rust on bolt		7
882892	2	rust on bolt		7
882893	2	rust on bolt		7
882894	2	rust on bolt		8
882895	2	rust on bolt		8
882880	1	Rust		9
882881	1	Rust		9
882882	1	Rust		10
882883	1	Rust		10
882884	1	Rust		10
882885	1	Rust		10
882886	1	Rust		10
882896	4	POI	Check here	11
882897	?	ID#	Visible	11

Power Line

File name:	DSC00033.JPG	Altitude:	80.86m
Date taken:	Aug 6, 2015 2:15:06 PM	Heading:	North (350.1°)
Position:	 57.0678832,10.0310435	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/10905?image=3460525



882878 Point of interest POI

Inspector:
Wear from vibration damper clamps

Power Line

File name:	DSC00034.JPG	Altitude:	83.71m
Date taken:	Aug 6, 2015 2:15:12 PM	Heading:	North (348.86°)
Position:	 57.0678944,10.0311259	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/10905?image=3460536




882879 Point of interest POI

Inspector:
AGS Clamp

Power Line

File name:	DSC00020.JPG	Altitude:	26.73m
Date taken:	Aug 6, 2015 3:27:09 PM	Heading:	East (80.36°)
Position:	 57.0670719,10.0274807	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/10905?image=3460543




882887 Severity: 2 rust on bolt



882888 Severity: 2 rust on bolt



882889 Severity: 2 rust on bolt



882890 Severity: 2 rust on bolt



882891 Severity: 2 rust on bolt



882892 Severity: 2 rust on bolt



882893 Severity: 2 rust on bolt



882894 Severity: 2 rust on bolt




882895 Severity: 2 rust on bolt

Power Line


File name:	DSC00023.JPG	Altitude:	25.64m
Date taken:	Aug 6, 2015 3:27:23 PM	Heading:	East (87.66°)
Position:	 57.0670520,10.0274370	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/10905?image=3460541



882880 Severity: 1 Rust




882881 Severity: 1 Rust



882882 Severity: 1 Rust




882883 Severity: 1 Rust



882884 Severity: 1 Rust




882885 Severity: 1 Rust



882886 Severity: 1 Rust

Power Line

File name:	DSC00012.JPG	Altitude:	82.42m
Date taken:	Aug 6, 2015 3:33:50 PM	Heading:	North (342.79°)
Position:	 57.0681611,10.0308575	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/10905?image=3460551



882896 Severity: 4 POI

Inspector:
Check here



882897 Point of interest ID#

Scopito:
Visible