



scopito

THE FUTURE OF VISUAL INSPECTIONS

Roof Inspection - Lollandsgade (dummy)

Report date:
Aug 5, 2020

Type:
Roof

Company:
Scopito Demo 1

Report images:
10

Annotations:
10



Severity overview

Severity 1

6

Severity 2

0

Severity 3

1

Severity 4

1

Severity 5

1

POI (?)

1

Roof Inspection - Lollandsgade (dummy) - Summary

Roof in very good condition however there are worn tiles in several areas.

A few cracked or broken tiles and a few slipped, the worse of the latter being the ridge tiles. There were a couple of roof tiles with holes in that need the most attention.

Annotation overview

Id	Severity	Issues	Comments	Page
444550	?	Loose tile	Ridge lifting and slipped slate	2
444517	1	Broken Slate		3
444518	1	Loose tile		4
444519	1	Loose tile	possible slipping tiles	5
444521	1	Broken Slate	Slate chipped needs some mortar	6
444523	5	Broken Slate	Hole in tile	7
444551	3	Loose tile	Ridge tile needs re-pointing	8
444525	1	Loose tile	loose ridge tile	9
444552	4	Broken Slate	hole in roof	10
444524	1	Small issue	loose ridge tile	11

Roof Inspection - Lollandsgade (dummy)

File name:	DJI_0331.JPG	Altitude:	7m
Date taken:	Jul 26, 2017 9:33:26 AM	Heading:	East (89.2°)
Position:	 56.1767767,9.5502683	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/92477?image=2570072



444550 Point of interest Loose tile

Luke Delbarre:
Ridge lifting and slipped slate

Roof Inspection - Lollandsgade (dummy)

File name:	DJI_0332.JPG	Altitude:	7.1m
Date taken:	Jul 26, 2017 9:33:30 AM	Heading:	East (89.1°)
Position:	 56.1767883,9.5502733	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/9247?image=2570073



444517 Severity: 1 Broken Slate

Roof Inspection - Lollandsgade (dummy)

File name:	DJI_0341.JPG	Altitude:	8.5m
Date taken:	Jul 26, 2017 9:34:54 AM	Heading:	East (85.3°)
Position:	 56.1768450,9.5502883	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/92477?image=2570082



444518 Severity: 1 Loose tile

Roof Inspection - Lollandsgade (dummy)

File name:	DJI_0342.JPG	Altitude:	8.8m
Date taken:	Jul 26, 2017 9:35:05 AM	Heading:	East (85.3°)
Position:	 56.1768433,9.5502867	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/9247?image=2570083



444519 Severity: 1 Loose tile

Luke Delbarre:
possible slipping tiles

Roof Inspection - Lollandsgade (dummy)

File name:	DJI_0349.JPG	Altitude:	8.4m
Date taken:	Jul 26, 2017 9:38:45 AM	Heading:	East (81.3°)
Position:	 56.1767733,9.5502900	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/9247?image=2570090



444521 Severity: 1 Broken Slate

Luke Delbarre:

Slate chipped needs some mortar

Roof Inspection - Lollandsgade (dummy)

File name:	DJI_0359.JPG	Altitude:	8.4m
Date taken:	Jul 26, 2017 9:39:52 AM	Heading:	North (352.4°)
Position:	 56.1767400,9.5503117	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/9247?image=2570100



444523 Severity: 5 Broken Slate


Luke Delbarre:
Hole in tile

Roof Inspection - Lollandsgade (dummy)

File name:	DJI_0366.JPG	Altitude:	9.3m
Date taken:	Jul 26, 2017 9:40:35 AM	Heading:	North (353.9°)
Position:	 56.1767700,9.5503250	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/9247?image=2570107



444551 Severity: 3 Loose tile

Luke Delbarre:
Ridge tile needs re-pointing

Roof Inspection - Lollandsgade (dummy)

File name:	DJI_0367.JPG	Altitude:	9.4m
Date taken:	Jul 26, 2017 9:40:38 AM	Heading:	North (354°)
Position:	 56.1767683,9.5503417	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/9247?image=2570108



444525 Severity: 1 Loose tile

Luke Delbarre:
loose ridge tile

Roof Inspection - Lollandsgade (dummy)

File name:	DJI_0403.JPG	Altitude:	6.5m
Date taken:	Jul 26, 2017 9:46:30 AM	Heading:	Southwest (208.9°)
Position:	 56.1768283,9.5503717	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/9247?image=2570144



444552 Severity: 4 Broken Slate

Luke Delbarre:
hole in roof

Roof Inspection - Lollandsgade (dummy)

File name:	DJI_0406.JPG	Altitude:	10.6m
Date taken:	Jul 26, 2017 9:47:09 AM	Heading:	South (172.7°)
Position:	 56.1768267,9.5503467	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/9247?image=2570147



444524 Severity: 1 Small issue

Luke Delbarre:
loose ridge tile

jkh

|k|kj|kl|k|kj|kl|k|kj|kl|k|kj|kl|k|kj|kl|k|kj|kl|k|kj|

hgfhfklkjlklklkjlkklkljlkklkljlkklkljlkklkljlkklkljlk

hgfhfklkjlklklkjlkklklkjlkklklkjlkklklkjlkklklkjlk

hgfhfklkljlkklkljlkklkljlkklkljlkklkljlkklkljlkklkljlk

hgfhfhlklkjljklklkjlkklkjlkklkjlkklkjlkklkjlkklkjlkklkjlk

hgfhfklkljlkklkljlkklkljlkklkljlkklkljlkklkljlkklkljlk

hgfhjflklkjlklklkjlklklkjlklklkjlklklkjlklklkjlklklkjlklklkjlklklkjlkl

hgfhjflklkjlkklkjljkklkjljkklkjljkklkjljkklkjljkklkjljk

hgfhjflklkjljklklkjlkklkjlkklkjlkklkjlkklkjlkklkjlkklkjlk

hgfhjflklkjljklklkjlkklkjlkklkjlkklkjlkklkjlkklkjlkklkjlk

hgfhfklkjlklkljlkklkljlkklkljlkklkljlkklkljlkklkljlk

hgfhjflklkjlkklkljlkklkljlkklkljlkklkljlkklkljlkklkljlk

hgfhf