



scopito

THE FUTURE OF VISUAL INSPECTIONS



scopito

THE FUTURE OF VISUAL INSPECTIONS



Report date:
Mar 10, 2020



Number of
annotations



Status:
Published



Type:
Power Line



Company:
Scopito Demo 1




Inspection created:
Aug 15, 2019



Report Images:
5



Report created by:
Ditte Rabæk
drl@scopito.com



Severity overview

Severity 1	Severity 2	Severity 3	Severity 4	Severity 5	POI (?)
7	9	0	1	0	3

💡 Inspection summary

This is a demo point inspection on various elements within the power grid.
This is where Summary can be added and edited.

For further information please contact info@scopito.com

Annotation overview


Id	Severity	Issues	Comments	Page
489842	?	POI	Wear from vibration damper clamps	4
489843	?	POI	AGS Clamp	5
489851	2	rust on bolt		6
489852	2	rust on bolt		6
489853	2	rust on bolt		7
489854	2	rust on bolt		7
489855	2	rust on bolt		7
489856	2	rust on bolt		7
489857	2	rust on bolt		7
489858	2	rust on bolt		8
489859	2	rust on bolt		8
489844	1	Rust		9
489845	1	Rust		9
489846	1	Rust		10
489847	1	Rust		10
489848	1	Rust		10
489849	1	Rust		10
489850	1	Rust		10
489860	4	POI	Check here	11
489861	?	ID#	Visible	11

Power Line

File name:	DSC00033.JPG	Altitude:	80.86m
Date taken:	Aug 6, 2015 4:15:06 PM	Heading:	North (350.1°)
Position:	 57.0678832,10.0310435	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/10151?image=3031349



489842 Point of interest POI

Inspector:
Wear from vibration damper clamps

Power Line

File name:	DSC00034.JPG	Altitude:	83.71m
Date taken:	Aug 6, 2015 4:15:12 PM	Heading:	North (348.86°)
Position:	 57.0678944,10.0311259	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/10151?image=3031360



489843 Point of interest POI

Inspector:
AGS Clamp

Power Line

File name:	DSC00020.JPG	Altitude:	26.73m
Date taken:	Aug 6, 2015 5:27:09 PM	Heading:	East (80.36°)
Position:	 57.0670719,10.0274807	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/10151?image=3031367




489851 Severity: 2 rust on bolt



489852 Severity: 2 rust on bolt



489853 Severity: 2 rust on bolt



489854 Severity: 2 rust on bolt



489855 Severity: 2 rust on bolt



489856 Severity: 2 rust on bolt



489857 Severity: 2 rust on bolt



489858 Severity: 2 rust on bolt




489859 Severity: 2 rust on bolt

Power Line


File name:	DSC00023.JPG	Altitude:	25.64m
Date taken:	Aug 6, 2015 5:27:23 PM	Heading:	East (87.66°)
Position:	 57.0670520,10.0274370	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/10151?image=3031365



489844 Severity: 1 Rust




489845 Severity: 1 Rust



489846 Severity: 1 Rust




489847 Severity: 1 Rust



489848 Severity: 1 Rust




489849 Severity: 1 Rust



489850 Severity: 1 Rust

Power Line

File name:	DSC00012.JPG	Altitude:	82.42m
Date taken:	Aug 6, 2015 5:33:50 PM	Heading:	North (342.79°)
Position:	 57.0681611,10.0308575	User tags:	No tags available



For a more detailed overview go to app.scopito.com/#/inspection/10151?image=3031375



489860 Severity: 4 POI

Inspector:
Check here



489861 Point of interest ID#

Scopito:
Visible